



Manifold Absolute Pressure/Pressure Sensor Wiring Terminations			
1, 2 & 3 Bar MAP			
	Gnd/Rtn	+5V	Signal
Terminal Location in Connector	A	C	B
Connect to BS3 Harness Wire Color	Black	Red	White/Blue
3 Bar MAP			
	Gnd/Rtn	+5V	Signal
Terminal Location in Connector	A	C	B
Connect to BS3 Harness Wire Color	Black	Red	White/Blue
4 Bar MAP			
	Gnd/Rtn	+5V	Signal
Terminal Location in Connector	A	B	C
Connect to BS3 Harness Wire Color	Black	Red	White/Blue
150 PSI Pressure Sensor			
	Gnd/Rtn	+5V	Signal
Terminal Location in Connector	A	B	C
Connect to BS3 Harness Wire Color	Black	Red	White/Blue